# Stock Information

1-Jun-26

| No. | WBS.No | Machine | Auto/Manual | Module | Vintage | Specification | | | | | | | | | Remark | Status |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | C/H | | Mg. | FM Unit | | | PC | Substrate Vacuum | Preheater | | deadline |
| | | | | | | Type | Size | | | Type | Size | | | | | |
| 1 | B-000086-01 | Y1E2060 | Auto | 1 | 2004 | - | - | ST | - | - | - | DOS | - | Fix type | RFH | ---------- |
| 2 | B-000126-01 | Y1E2060 | Auto | 4 | 2002 | ○ | Y-STH-U-M-PIN | ST | - | - | - | Windows | - | Fix type | Movable pin unit removed | ---------- |
| 3 | B-000130-01 | Y1E2120 | Auto | 2 | 2000 | - | - | Non | - | - | - | Windows | - | Fix type | Without Out M/G | ---------- |
| 4 | B-000132-01 | PMC1040D Lot5-OC | Press only | 1 | 2018 | - | - | Non | - | - | - | - | - | - | | Sold Out |
| 5 | B-000139-01 | Y1E2080 | Auto | 2 | 2004 | ○ | L | ST | - | - | - | Windows | - | Fix type | | ---------- |
| 6 | B-000140-01 | Y1E2080 | Auto | 2 | 2005 | ○ | L | ST | - | - | - | Windows | - | Fix type | | ---------- |
| 7 | B-000142-01 | Y1E2080 | Auto | 1 | 2008 | ○ | L | ST | - | - | - | Windows | - | Up / Down | | ---------- |
| 8 | B-000141-01 | Y1E2080 | Auto | 2 | 2007 | ○ | L | ST | - | - | - | Windows | - | Up / Down | | ---------- |
| 9 | B-000144-01 | Y1R1080 | Auto | 1 | 2018 | ○ | L | ST | - | - | - | Windows | - | Up / Down | | ---------- |
| 10 | B-000149-01 | Y1E2060 | Auto | 3 | 2002 | ○ | M | ST | - | - | - | DOS | - | Fix type | | ---------- |
| 11 | B-000150-01 | Y1E2060 | Auto | 3 | 2003 | ○ | M | ST | - | - | - | DOS | - | Fix type | | ---------- |
| 12 | B-000151-01 | Y1E2060 | Auto | 3 | 2007 | ○ | M | ST | - | - | - | Windows | - | Fix type | | ---------- |
| 13 | B-000154-01 | PMC1040S | Auto | 4 | 2018 | - | - | SL | - | - | - | Windows | - | - | | ---------- |
| 14 | B-000155-01 | PMC1040S | Auto | 4 | 2018 | - | - | SL | - | - | - | Windows | - | - | | ---------- |
| 15 | B-000156-01 | PMC1040S | Auto | 4 | 2017 | - | - | SL | - | - | - | Windows | - | - | | Sold Out |
| 16 | B-000158-01 | FFT1030G | Auto | 1 | | - | - | SL | - | - | - | Windows | - | - | | |

【Warranty period】
※ The standard warranty period is 3 months after delivery of the system.
※ There is no warranty when ordering with AS IS.

【Shipping cost】
※ Domestic shipping costs and F.O.B. charges will be added separately.

# Urgently Wanted Equipment

| No. | WBS.No | Machine | Auto/Manual | Module | Vintage | Specification | | | | | | | | Remark | Business negotiation |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | C/H | | Mg. | FM | | | PC | Substrate Vacuum | Preheater | | deadline |
| | | | | | | | Size | | | Type | Size | | | | | |
| 1 | | YPM | | | | | | | | | | | | | | ---------- |
| 2 | | PMC | | | | | | | | | | | | | | ---------- |
| 3 | | LCM | | | | | | | | | | | | | | ---------- |
| 4 | | | | | | | | | | | | | | | | ---------- |
| 5 | | | | | | | | | | | | | | | | ---------- |
| 6 | | | | | | | | | | | | | | | | ---------- |
| 7 | | | | | | | | | | | | | | | | ---------- |